


Location: Melton Road/Fishpool Way Roundabout

Task # 26

Date: 5th September **Review Date:** Feb 20

Map:



Looking up Melton Road from Poppyfields roundabout. Before the task the hedges were getting overgrown and beginning to obstruct the pavements. We cut back along the nearside edge of the pavements and right back into the hedge where possible.



Further up Melton Road, before, the road signs were getting difficult to see, and after, much clearer. Over hanging hedges and branches cut back and left under the remaining hedgerow to provide winter habitat.



Top of Melton Road near the roundabout on Fishpool Way. Again, overhanging branches and bramble cut back, Ivy growing alongside the pavement and beginning to encroach over it was cut back. Pavements swept and leaf debris cleared, including on the road edge.

Litter picking before and during the task produced 2 large bags of rubbish just from this short patch of roadside.